PAGE: 1 PRINT DATE: 11/16/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 03-1-0144 -X

SUBSYSTEM NAME: MAIN PROPULSION

REVISION: 2 02/21/01

PART DATA

PART NAME PART NUMBER
VENDOR NAME VENDOR NUMBER

LRU: LINE ASSEMBLY V070-415770

BOEING

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

LINE ASSEMBLY, HELIUM BLOWDOWN, 750 PSIA PNEUMATIC HELIUM, FROM HELIUM SUPPLY BLOWDOWN SOLENOID VALVE (LV27) TO PURGE, VENT, AND DRAIN ORIFICE. THE LINE ASSEMBLY CONSISTS OF DYNATUBE FITTINGS, UNIONS, SEALS, AND TUBE SEGMENTS.

REFERENCE DESIGNATORS:

QUANTITY OF LIKE ITEMS: 1

FUNCTION:

PROVIDES THE FLOW PATH FOR HELIUM FROM THE DOWNSTREAM BLOWDOWN VALVE (LV27) TO THE BLOWDOWN ORIFICE ASSEMBLY FOR PURGING THE AFT AND OMS/RCS COMPARTMENT DURING ENTRY.

PAGE 2 PRINT DATE: 11/27/01

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 03-1-0144-01

REVISION#: 2 02/21/01

SUBSYSTEM NAME: MAIN PROPULSION

LRU: GHE BLOWDOWN VALVE OUTLET LINE ASSY
ITEM NAME: GHE BLOWDOWN VALVE OUTLET LINE ASSY
FAILURE MODE: 1/1

FAILURE MODE:

RUPTURE/LEAKAGE.

MISSION PHASE: LO LIFT-OFF

DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA

103 DISCOVERY104 ATLANTIS105 ENDEAVOUR

CAUSE:

MATERIAL DEFECT, FATIGUE, DEFECTIVE BRAZE JOINTS, DAMAGED/DEFECTIVE JOINT SEALS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) N/A

B) N/A

C) N/A

PASS/FAIL RATIONALE:

A)

B)

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

DURING ENTRY, VENT DOORS ARE CLOSED TO PREVENT INGESTION OF RCS AND APU GASES. RUPTURE DURING THE TIME PERIOD THAT THE VENT DOORS ARE CLOSED AND THE AFT COMPARTMENT PURGE IS COMMANDED ON (5300 FT/SEC) MAY RESULT IN OVERPRESSURIZATION OF AFT COMPARTMENT. VENT DOORS ARE OPENED WHEN VEHICLE VELOCITY DROPS BELOW 2400 FT/SEC.

PAGE: 3 PRINT DATE: 11/27/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0144-01

(B) INTERFACING SUBSYSTEM(S):

SAME AS A.

(C) MISSION:

POSSIBLE LOSS OF CREW/VEHICLE.

(D) CREW, VEHICLE, AND ELEMENT(S):

SAME AS C.

(E) FUNCTIONAL CRITICALITY EFFECTS:

1R/3 3 SUCCESS PATHS. TIME FRAME - PRELAUNCH, ASCENT, DE-ORBIT PRIOR TO 5300 FT/SECOND.

- 1) LINE RUPTURES.
- 2,3) BOTH BLOWDOWN VALVES (LV26,27) FAIL TO REMAIN CLOSED.

RESULTS IN LOSS OF PNEUMATIC HELIUM SUPPLY. HELIUM PRESSURE WILL NOT BE AVAILABLE TO CLOSE THE PREVALVES AT MECO OR THE ET/ORBITER UMBILICAL DISCONNECTS PRIOR TO ET SEPARATION. DISCONNECTS WILL CLOSE IN MECHANICAL BACKUP MODE DURING UMBILICAL RETRACT. FAILURE TO CLOSE THE LO2 PREVALVES AT MECO WILL RESULT IN UNCONTAINED ENGINE DAMAGE. RESULTS IN THE INABILITY TO MAINTAIN INJECTED HELIUM AND LO2 PRESSURE AT THE SSME PUMP, RESULTING IN POSSIBLE PUMP OVERSPEED AND EXPLOSION. POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND FIRE/EXPLOSIVE HAZARD.

ENGINE HELIUM SUPPLY SYSTEM IS CONNECTED TO VALVE ACTUATION SUPPLY BY THE CROSSOVER VALVE (LV10) AT MECO BY SOFTWARE COMMAND. THE ADDITIONAL HELIUM SUPPLY MAY NOT ACTUATE LO2 PREVALVES CLOSED.

EXCESSIVE HELIUM LEAKAGE WILL BE DETECTABLE USING HAZARDOUS GAS DETECTION SYSTEM (HGDS).

RESULTS IN LOSS OF PNEUMATIC AND LEFT ENGINE HELIUM SUPPLY IF THE FAILURE OCCURS AFTER THE LEFT ENGINE HELIUM CROSSOVER VALVE (LV10) OPENS AT MECO. LOSS OF PNEUMATIC, E1 AND E3 HELIUM SUPPLIES IF FAILURE OCCURS WHILE THE E1 AND E3 INTERCONNECT "OUT" VALVES (LV60 AND 64) AND LV10 ARE OPEN, BEGINNING AT MECO+20 SECONDS.

HELIUM WILL NOT BE AVAILABLE FOR AFT COMPARTMENT PURGE.

POSSIBLE LAUNCH SCRUB DUE TO LCC VIOLATION.

POSSIBLE LOSS OF CREW/VEHICLE.

-DISPOSITION RATIONALE-

PAGE: 4 PRINT DATE: 11/27/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0144-01

(A) DESIGN:

THE LINE IS DESIGNED TO A MINIMUM FACTOR OF SAFETY OF 2.0 PROOF AND 4.0 BURST. THE MECHANICAL FITTINGS (DYNATUBE) ARE MANUFACTURED FROM INCONEL 718 WITH TUBE ENDS THAT ARE NICKEL PLATED. THE TUBE SEGMENTS ARE MANUFACTURED FROM 304L CRES TUBING 3/8 INCH DIAMETER BY 0.020 INCH WALL THICKNESS.

THE DYNATUBE FITTINGS ARE CONNECTED TO THE COMPONENTS USING UNIONS MADE OF INCONEL 718 (ME273-0115) AND METALLIC BOSS SEALS (ME261-0063 TYPE III) FABRICATED FROM A286 CORROSION RESISTANT STEEL COATED WITH K-6 NICKEL LEAD. THE TUBE SEGMENTS AND FITTINGS ARE JOINED BY INDUCTION BRAZING USING 21-6-9 CRES UNIONS AND BRAZE ALLOY PREFORMS (81.5 AU, 16.5 CU, 2 NI). THE ROCKWELL INTERNATIONAL BRAZE ALLOY WAS SELECTED BECAUSE OF ITS LOWER BRAZING TEMPERATURE REQUIREMENT THAN THE INDUSTRY STANDARD, AIDING IN THE PREVENTION OF EXCESSIVE GRAIN GROWTH AND REDUCING EROSION OF TUBE ENDS.

(B) TEST:

ATP

THE LINE IS PROOF PRESSURE TESTED TO 1500 PSIG AND LEAK CHECKED AT 750 PSIG DURING PANEL ASSEMBLY ACCEPTANCE TEST.

CERTIFICATION

CERTIFICATION OF THE TUBING INSTALLATION WAS ACCOMPLISHED BY ROCKWELL INTERNATIONAL PER THE "ORBITER TUBING VERIFICATION PLAN SD75-SH-205".

THE 304L CRES TUBING WAS CERTIFIED FOR THE APOLLO PROPULSION SYSTEMS, THE F5E, A-9, C130A, 707, 727, AND 737 AIRCRAFT. THE TUBING WAS QUALIFIED BY SIMILARITY AND BY ANALYSIS FOR ORBITER USAGE EXCEPT FOR FLEXURE FATIGUE AND RANDOM VIBRATION FOR THE LONG-LIFE ORBITER REQUIREMENTS. DATA FROM THE MISSION DUTY CYCLES CONDUCTED ON MPTA WERE ALSO USED TO CERTIFY TUBING INSTALLATIONS.

304L CRES TUBING WITH DYNATUBE FITTINGS AND SEALS WAS SUBJECTED TO THE FOLLOWING QUALIFICATION TESTS:

PROOF PRESSURE
TWO TIMES OPERATING PRESSURE

EXTERNAL LEAKAGE AT 1.5 TIMES OPERATING PRESSURE 1X10-6 SCCS MAX

IMPULSE FATIGUE (200,000 CYCLES)

FLEXURE FATIGUE (10 MILLION FLEXURE CYCLES)

VIBRATION (7 UNITS) 45 MINUTES AT 0.4 G2/HZ 30 MINUTES AT 0.7 G2/HZ 10 MINUTES AT 0.2 G2/HZ PAGE: 5 PRINT DATE: 11/27/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0144-01

BURST TEST

FOUR TIMES OPERATING PRESSURE

OMRSD

ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

RECEIVING INSPECTION

ALL DETAIL HARDWARE IS VERIFIED INDIVIDUALLY, BY INSPECTION. RAW MATERIALS ARE VERIFIED BY INSPECTION FOR MATERIAL AND PROCESS CERTIFICATION.

CONTAMINATION CONTROL

CLEANLINESS LEVEL IS VERIFIED TO 100A. CORROSION PROTECTION IS VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

PARTS PROTECTION FROM DAMAGE AND CONTAMINATION IS VERIFIED. DETAIL HARDWARE ARE INSPECTED VISUALLY DURING FABRICATION. AXIAL ALIGNMENT OF DYNATUBE FITTINGS AND TUBING IS VERIFIED. TORQUES AND SEALING SURFACES ARE VERIFIED BY INSPECTION. LUBRICATION OF ALL THREADED FLUID FITTING COUPLINGS IS VERIFIED. MANDATORY INSPECTION POINTS ARE INCLUDED IN THE ASSEMBLY PROCEDURES.

CRITICAL PROCESSES

ELECTRICAL BONDING AND PARTS PASSIVATION ARE VERIFIED BY INSPECTION. INDUCTION BRAZING IS VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

RADIOGRAPHIC INSPECTION OF INDUCTION BRAZED JOINTS IS VERIFIED.

TESTING

ATP IS VERIFIED BY INSPECTION.

HANDLING/PACKAGING

PACKAGING FOR SHIPMENT IS VERIFIED BY INSPECTION.

(D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURE, FLIGHT FAILURE, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

(E) OPERATIONAL USE:

DURING THE ENTRY TIME FRAME, THE CREW MAY BE DIRECTED (UPON GROUND CALL) TO CLOSE THE PNEUMATIC ISOLATION VALVES (LV7,8) AND THE CROSSOVER VALVE (LV10).

PAGE: 6 PRINT DATE: 11/27/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0144-01

- APPROVALS -

S&R ENGINEERING : W.P. MUSTY :/S/ W. P. MUSTY

S&R ENGINEERING ITM : P. A. STENGER-NGUYEN :/S/ P. A. STENGER-NGUYEN
DESIGN ENGINEERING : LEE DURHAM :/S/ LEE DURHAM MPS SUBSYSTEM MGR. : TIM REITH :/S/ TIM REITH
MOD : JEFF MUSLER :/S/ JEFF MUSLER
USA SAM : MIKE SNYDER :/S/ MIKE SNYDER
USA ORBITER ELEMENT : SUZANNE LITTLE :/S/ SUZANNE LITTLE
NASA SR&QA : BILL PRINCE :/S/ BILL PRINCE